Factory Seconds Pool Shells - Call 1300 652 710 For More Info

Note: Factory Seconds pools have slight cosmetic defects that are usually very hard to detect. The discount reflects the level of defect.

Note: All pool shells come with a lifetime structural warranty (35 years)

Note: Marbletech gelcoat colours have a 20 year cosmetic warranty.

Note: Freight costs not included in the prices listed. **Please call for a quote.**

Note: Please contact 1300 652 710 for shell only prices

Current As Of: 15 September 2025

QUEENSLAND/NEW SOUTH WALES

	Pool Model (Click To View)	Colour	Pool Image	Video	DISCOUNT (From Kit Price)	Fittings Included	Structural Warranty	Status	Reason
Factory Seconds									
	Whitsunday 6.5	Marbletech™ Alabaster		Click Here to View Video	\$ 2,750.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	Available	Full Structural and Cosmetic Warranty. The gelcoat colour is less consistent on the left side of the pool and in one section of the shallow end pool wall. Gelcoat layer is full thickness however the left side is lighter in colour.
	Whitsunday 6.5	Marbletech™ Alabaster		Click Here to View Video	\$ 3,338.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	Available	Full Structural and Cosmetic Warranty. Small section of the horizontal surface of the bench seat is lighter in colour. This will be visible when filled with water.
	<u>Hayman 6</u>	<u>Marbletech™ Teal</u>	r'e		\$ 2,603.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	SOLD	Full Structural and Cosmetic Warranty. Resin bleed through spot top and slightly rough gelcoat to right handside step. Resin bleed through spots above the waterline near the side seat area. Resin spots will be sanded smooth. The spots above the waterline will be visible if looking for them.
	Whitsunday 7	Marbletech™ Sky Pearl		Click Here to View Video	\$ 3,633.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	On Hold	Full Structural and Cosmetic Warranty . Visible black dots through gelcoat in the left side radius near the deep end. 1.5m section of lighter gelcoat in the radius. This will be visible when filled with water.
	Whitsunday 7	Marbletech™ Emerald Pearl			\$ 2,373.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	Available	Full Structural and Cosmetic Warranty. Impact damage repair to bottom of right hand steps. Barely noticeable and only if looking for it.
	<u>Hayman 7</u>	<u>Marbletech™</u> <u>Mediterranean</u>			\$ 2,250.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	Available	Full Structural and Cosmetic Warranty. Slight depression around the top of the pool wall. Will be difficult to detect when filled with water and pavers laid.



	Pool Model (Click To View)	Colour	Pool Image			Fittings (Drilled and Supplied)	Structural Warranty	Status	Reason
/ICTORIA									
actory Seconds None Available									
	Pool Model (Click To View)	Colour	Pool Image			Fittings (Drilled and Supplied)	Structural Warranty	Status	Reason
OUTH AUSTRALIA									
	<u>Hayman 9</u>	<u>Marbletech™ Cascade</u>		Click Here to View Video	\$ 4,029.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	Available	Full Structural and Cosmetic Warranty. The outside of the shell was hit by a crane lifting strap buckle. This has caused a very small area of spiral cracking to the gelc inside the shell. Raised part of the crack will be repaired smooth however the cramight be visible in certain light conditions
	<u>Daintree 8</u>	Marbletech™ Moonlight Oyster		Click Here to View Video	\$ 3,878.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled. Includes Infloor Cleaning.	35 years	Available	Full Structural and Cosmetic Warranty . Shell was hit by another pool in the yard which fractured the gelcoat. The repair is not visible.
	Whitsunday 8	<u>Mystic Shimmer</u>			\$ 3,000.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 Years	Available	Full Structural and Cosmetic Warranty. Gelcoat stripey along the floor - this won' be noticeable when filled with water. Full length mould marks in the shallow end radius, which will be noticeable when filled with water . All other marks are from storage and will polish to as new. Solar return above middle step rightside. Requir solar suctions in deep end. Also has three light holes drilled so will require 3 lights
	Whitsunday 8	Marbletech™ Cascade		Click Here to View Video	\$ 2,000.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	Available	Full Structural and Cosmetic Warranty. Repaired spider cracks to the radius in fro of both sets of steps and right hand side deep end wall. This is from the pool shell being stored incorrectly at the installation site. Still visible post-repair and will be visible once they fill with dirt from normal pool use.
	Hayman 8	<u>Marbletech™ Regent</u>		Click Here to View Video	\$ 2,500.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 years	Available	Full Structural and Cosmetic Warranty. Lots of black gelcoat dots on the vertical for the bench seat over a 1m section. This will be visible in certain light conditions.
	Hayman 8	Atlantic Shimmer			\$ 3,000.00	Skimmer Box, Return Jets, Hydro Valve - All Holes Drilled	35 Years	Available	Full Structural and Cosmetic Warranty. Visible large repair to left wall. Highly shimmered. Mould marks above the right side top step. Mould marks in deep encradius near hydo valve. Large star crack below foot ledge near right side steps. Wi be visible when filled with water. Drilled for solar fittings.

WESTERN AUSTRALIA											
	Pool Model (Click To View)	Colour	Colour With and Without Water		Fittings	Structural Warranty	Status	Reason			
Factory Seconds					•	•					
None Available											

PLEASE SEE NEXT PAGE FOR AVAILABLE STOCK POOLS

Stock Pool Shells - Call 1300 652 710 For More Info

Note: Customer Cancelled Orders are brand new shells ordered by a customer / Factory Stock Pools are brand new shells supplied by the factory

Note: Marbletech gelcoat colours have a 20 year cosmetic warranty.

Note: Freight costs not included in the prices listed. **Please call for a quote.**

Note: Please contact 1300 652 710 for shell only prices

Current As Of: 15 September 2025

BRAND NEW STOCK POOLS ARE LISTED SEPARATELY AFTER THE FACTORY SECONDS POOLS

QUEENSLAND/NEW SOUTH WALES

	Pool Model (Click To View)	Colour	DISCOUNT (From Kit Price)	Structural Warranty	Status	Reason
Brand New Factory Stock Pools						
	Whitsunday 4.5	<u>Mystic Shimmer</u>	\$ 500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Whitsunday 4.5	<u>Mystic Shimmer</u>	\$ 500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Whitsunday 4.5	<u>Mystic Shimmer</u>	\$ 500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Daintree 6	<u>Marbletech™ Cascade</u>	\$ 500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new



	Whitsunday 6.5	<u>Marbletech™ Blue Steel</u>	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Whitsunday 6.5	Ocean Sand Shimmer	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Whitsunday 7	Marbletech Pacific Pearl	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	<u>Daintree 8</u>	Mystic Shimmer	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Whitsunday 8	Marbletech Granite	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Hayman 9 with In-floor Cleaning	<u>Marbletech™ Crystal</u>	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	<u>Daintree 10</u>	Marbletech Mediterranean	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
	Broome 6-Seater Spa	Marbletech™ Midnight Sparkle	\$ 5	500.00	35 Years	Available	Manufacturer Surplus Stock. Brand new
SOUTH AUSTRALIA							

	Pool Model (Click To View)	Colour	DISCOUNT	Structural Warranty	Status	Reason
Brand New Factory Stock Pools						
None Available						
VICTORIA						
	Pool Model (Click To View)	Colour	DISCOUNT	Structural Warranty	Status	Reason
Factory Stock Pools						
	<u>Hayman 6</u>	<u>Marbletech™ Crystal</u>	FREE AquaGuard-X™ Marbletech™ Upgrade Worth \$1,150	35 Years	Available	Manufacturer Surplus Stock. Brand new
	<u>Daintree 7</u>	Marbletech™ Regent	FREE AquaGuard-X™ Marbletech™ Upgrade Worth \$1,250	35 Years	Available	Manufacturer Surplus Stock. Brand new
	<u>Hayman 7</u>	Mystic Shimmer	\$ 2,000.00	35 years	Available	Manufacturer Surplus Stock. Brand new
	<u>Bondi 7.2</u>	<u>Marbletech™ Whitehaven</u>	FREE AquaGuard-X™ Marbletech™ Upgrade Worth \$1,250	35 Years	Available	CFPK Cancelled Order
	Hayman 8	Marbletech™ Crystal	FREE AquaGuard-X™ Marbletech™ Upgrade Worth \$1,300	35 Years	Available	Manufacturer Surplus Stock. Brand new
WESTERN AUSTRALIA						
	Pool Model (Click To View)	Colour		Structural Warranty	Status	Reason
Cancelled Orders						
	None Available					